


Aluminum

2 Required

.312 hole to be line bored while retainers are mounted on frame.

Dia. to fit 5/16 OD X 3/16 ID crank shaft bushing.



Lakeshore  
Machine & Repair

8677 Paradise Beach Rd.  
Greiner, N.H. 03041

This print is not for sale.  
It may be distributed freely  
for any noncommercial use.

DRAWN	A Tougas	DATE	02/20/2010
CHECKED			
DESIGN			

DWG NAME	Crank Retainer
SIZE	DWG NO.
SCALE	None
SHEET	1A OF 1
REV	B